



<b>FORD Mondeo: 1ENF522</b>			
Vinnnumber:	<b>WF0GXXG8BGC578101</b>	Versionname:	<b>MONDEO CLIP Econetic Titanium 115PK</b>
First Registrationdate:	<b>29/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>182188</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2412</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>215/55/16/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 6 mm</b>	Fr.R.	<b>Dunlop: 6 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1105,20</b>
<b>Door R R, Scratch(es), LI - Repair and paint (complete)</b>	<b>0,00</b>



<b>Door F R, Scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>
--	---------------



<b>Alloy rim F R, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>
---	--------------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Sill outer L, Bump(s), LI - Repair and paint (complete)	310,50
---	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

*No pictures to display*

Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------

