



VOLKSWAGEN Passat: 1EQM968			
Vinnnumber:	WVWZZZ3CZDP037108	Versionname:	PASSAT BER Comfortline BMT 105PK
First Registrationdate:	23/02/2013	Fiscalpower:	
Expertise Mileage:	114990	Power Kw:	77
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2624
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	1189,10
Bumper grille, Damaged, E - Replace	32,40







Windscreen, Scratch(es), E - Replace	0,00
--------------------------------------	-------------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
	
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
	
Door F R, Bump(s), LI - Repair and paint (complete)	318,35
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	