


TOYOTA Auris: 1FKW759

Vinnnumber:	SB1ZS3JE50E034259	Versionname:	AURIS TOUR.SP. HSD Premium CVT 99PK Aut.
First Registrationdate:	1/08/2013	Fiscalpower:	
Expertise Mileage:	165848	Power Kw:	73
Bodytype:	Break	Body color	Dark Red
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1608
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunction	Type of Tow bar	Tow bar removable
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1640,73
-------------------	----------------

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Broken, Le - Replace and paint	651,00
--	---------------



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 268,18



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display