



SKODA Octavia: 1GAA718			
Vinnumber:	TMBJG7NE5E0113365	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	3/12/2013	Fiscalpower:	
Expertise Mileage:	183898	Power Kw:	77
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2533
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm


Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2214,46
Rearlight L, Crack, E - Replace			114,00



Trunk lid covering R, Scratch(es), E - Replace	64,00
--	--------------



Door R L, Bump(s), LI - Repair and paint (complete)	318,35
---	---------------



Wing R R, Bump(s) and scratch(es), Le - Replace and paint 1231,51



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Repaired, Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display