



VOLKSWAGEN GOLF break: 1CLN958

Vinnumber:	WVWZZZ1JZ6W019459	Versionname:	
First Registrationdate:	4/04/2006	Fiscalpower:	
Expertise Mileage:	230237	Power Kw:	74
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1522
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Windows electric R	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS base
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 2189,23

Rear window, Scratch(es), E - Replace 370,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Centre console, Missing, Repair/replace (lump sum) 10,00



Instrument panel complete, Not functioning (well), Acceptable 0,00



Luggage space cover, Missing, E - Replace 240,00



Bonnet, Stone chip(s), LI - Repair and paint (complete) 290,08



Windscreen, Tear, E - Replace

487,20

