



**VOLKSWAGEN Golf: 1EHW113**

|                         |                          |              |   |
|-------------------------|--------------------------|--------------|---|
| Vinnnumber:             | <b>WVWZZZ1KZDM643859</b> | Versionname: | <b>GOLF BRE Highl.BM DPF DSG 105PK Aut.</b> |
| First Registrationdate: | <b>7/12/2012</b>         | Fiscalpower: |   |
| Expertise Mileage:      | <b>149652</b>            | Power Kw:    | <b>77</b>                                   |
| Bodytype:               | <b>Break</b>             | Body color   | <b>Light Grey</b>                           |
| Gearbox:                | <b>Automatic</b>         | Paint type   | <b>Metalic</b>                              |
| Transmission:           |                          | Rims summer  | <b>Aluminium</b>                            |
| Fueltype:               | <b>Diesel</b>            | Oil level    | <b>OK</b>                                   |
| Battery functioning     | <b>Yes</b>               | Parking lot  | <b>2431</b>                                 |
| Number of doors         | <b>5</b>                 |              |   |
| Number of seats         | <b>5</b>                 |              |   |
| Number head rests       | <b>5</b>                 |              |   |
| Rims summer             | <b>Aluminium</b>         |              |   |
| Category                | <b>Passenger Car</b>     |              |   |
| Oil level               | <b>OK</b>                |              |   |

**Options**

|                                |  |
|--------------------------------|--|
| Radio CD                       | Central consol F                         |
| Windows electric F             | Luggage cover                            |
| Windows electric R             | Front parking sensors                    |
| Cruise Control                 | Rear parking sensors                     |
| Steering wheel multifunctional | Type of Tow bar <b>Tow bar removable</b> |
| Type of headlighting           | <b>Headlighting Halogen</b>              |
| Type of GPS                    | <b>GPS big screen color</b>              |
| Type of Lining                 | <b>Lining Alcantara</b>                  |
| Type of climate control        | <b>Autom climate control</b>             |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

**Degree of wear**

|               |                                  |                     |       |                     |
|---------------|----------------------------------|---------------------|-------|---------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                     |       |                     |
| Winter tyres: | Fr.L.                            | <b>Kleber: 7 mm</b> | Fr.R. | <b>Kleber: 7 mm</b> |
|               | Re.L.                            | <b>Kleber: 7 mm</b> | Re.R. | <b>Kleber: 7 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>1343,95</b> |
|-------------------|----------------|

|                                   |             |
|-----------------------------------|-------------|
| Tailgate, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|   |              |
|---|--------------|
| Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|---|--------------|



|   |               |
|---|---------------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | <b>318,35</b> |
|---|---------------|



|   |              |
|---|--------------|
| Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|---|--------------|



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper grille F L, Missing, E - Replace

74,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper grille, Damaged, E - Replace

74,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Outer valance R, Missing, Le - Replace and paint

74,00

