



**VOLKSWAGEN Golf: 1GHG264**

Vinnumber:	<b>WVWZZZAUZEP560098</b>	Versionname:	<b>GOLF VAR Highline DSG 105PK Aut.</b>
First Registrationdate:	<b>7/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>160340</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3401</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1222,53
-------------------	---------

Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door seal R, Tear, E - Replace	35,00
--------------------------------	-------



	333,53
--	--------

Sill outer L, Bump(s), LI - Repair and paint (complete) 310,50



Door R R, Bump(s), Acceptable 0,00

*No pictures to display*

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s), Acceptable 0,00

*No pictures to display*

Tailgate, Bump(s), LI - Repair and paint (complete) 301,68



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Window F R door, Scratch(es), E - Replace 99,00

