




VOLKSWAGEN Golf: 1EQW601			
Vinnnumber:	WVWZZZAUZDP046069	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	26/02/2013	Fiscalpower:	
Expertise Mileage:	198214	Power Kw:	77
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3224
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control
Adaptive cruise control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	185/65/15/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 1 mm	Fr.R.	Continental: 1 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment	
Spare tyre compact	Yes Jack Yes
Total cost ex VAT	534,20
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s), PDR - Knock out without painting	63,00



Interior, Dirty, Cleaning	100,00
---------------------------	---------------





Door F R, Difference in color, Acceptable	0,00
---	------



Wing R L, Bump(s), LI - Repair and paint (complete)	356,20
---	--------



Outer door handle F L, Incomplete, E - Replace	15,00
--	-------

