


**VOLKSWAGEN Touran: 1FRI265**

Vinnnumber:	<b>WVGZZ1TZEW028435</b>	Versionname:	<b>TOURAN Trendline BMT</b>
First Registrationdate:	<b>1/10/2013</b>	Fiscalpower:	<b>Start/Stop 105PK</b>
Expertise Mileage:	<b>148034</b>	Power Kw:	<b>77</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4220</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**


	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Michelin: 8 mm</b>	Re.R.	<b>Michelin: 8 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1502,18</b>
-------------------	----------------

Bonnet, Chemical polution, LI - Repair and paint (complete)	<b>290,08</b>
---	---------------



Tailgate, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

No pictures to display

Alloy rim R R polished, Damaged, E - Replace	<b>235,20</b>
--	---------------



Seat cover F L, Stain, Cleaning 25,00




Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F L polished, Damaged, E - Replace 235,20



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R L polished, Damaged, E - Replace 235,20



Bumper F R, Scratch(es), Acceptable 0,00

*No pictures to display*