



VOLKSWAGEN Sharan: 1GGT172

Vinnnumber:	WVWZZZ7NZEV021443	Versionname:	SHARAN Comfortline BMT
First Registrationdate:	4/02/2014	Fiscalpower:	136PK
Expertise Mileage:	123319	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2223
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Runflat **Yes**

Total cost ex VAT	1244,03
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Shutter / cover, Missing, E - Replace	50,00

Outer backrest protection R, Scratch(es), Acceptable **0,00***No pictures to display*Wing F L, Scratch(es), LI - Repair and paint (complete) **312,21**



Bumper grille, Broken, E - Replace

34,08



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

254,16



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

478,02



Door F L, Bump(s) and scratch(es), Acceptable

0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Front bumper, Scratch(es), It - Spot repair

115,56

