



VOLKSWAGEN Touran: 1ENU586			
Vinnnumber:	WVGZZZ1TZDW074284	Versionname:	TOURAN Trendline BMT Start/Stop 105PK
First Registrationdate:	1/02/2013	Fiscalpower:	
Expertise Mileage:	93513	Power Kw:	77
Bodytype:	MPV	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1509
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment	
Total cost ex VAT	1480,58
Wing R L, Bump(s), PDR - Knock out without painting	63,00



Bumper grille, Broken, E - Replace	32,40
------------------------------------	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), LI - Repair and paint (complete) 290,08



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

