



VOLVO V60: 1GGX556

Vinnnumber:	YV1FW31A1E1195245	Versionname:	V60 BRE D3 Kinetic 136PK
First Registrationdate:	5/02/2014	Fiscalpower:	
Expertise Mileage:	113184	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1513
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	NOT OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/50/17/95 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Other: 8 mm	Re.R.	Other: 8 mm

Assistance equipment

Compressor	Yes
------------	------------

Total cost ex VAT	982,78
-------------------	---------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
-------------------------------------------------------------	---------------



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper grille, Damaged, E - Replace 54,00



Wing F R, Bump(s), LI - Repair and paint (complete) 220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

