



VOLVO V60: 1GHM936			
Vinnumber:	YV1FW73CDE1194922	Versionname:	V60 BRE D4 Kinetic Geartr.181PK Aut.
First Registrationdate:	10/02/2014	Fiscalpower:	
Expertise Mileage:	128736	Power Kw:	133
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2125
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	NOT OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/50/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Fulda: 9 mm	Re.R.	Fulda: 9 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			496,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

