



VOLVO V70: 1HUH747

Vinnnumber:	YV1BW73C1F1320650	Versionname:	V70 D4 Polar 181PK
First Registrationdate:	6/10/2014	Fiscalpower:	
Expertise Mileage:	173792	Power Kw:	133
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2211
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/16/99 H LightMetal			
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1433,87
Rearview mirror housing R, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing L, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Windscreen, Damaged, E - Replace			560,64



Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door panel R R, Tear, E - Replace	132,00
-----------------------------------	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display