



VOLVO V60: 1RGD344			
Vinnnumber:	YV1FW74C1H1357227	Versionname:	2.0 D2 DYNAMIC EDITION
First Registrationdate:	15/12/2016	Fiscalpower:	
Expertise Mileage:	12366	Power Kw:	88
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1525
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/50/17/95 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1360,55
Rearview mirror housing L, Damaged, E - Replace	24,00



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
--	---------------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------

