



VOLKSWAGEN Golf: 1EM995			
Vinnumber:	WVWZZZ1KZDM651668	Versionname:	GOLF BRE Highline BlueMot.DPF 105PK
First Registrationdate:	28/01/2013	Fiscalpower:	
Expertise Mileage:	143870	Power Kw:	77
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2323
Number of doors:	5		
Number of seats:	5		
Number head rests:	3		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 T LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	1334,10
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Headrest R L, Missing, E - Replace 60,00



Headrest R R, Missing, E - Replace 60,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 100,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



