


AUDI A6: 1GCV760

Vinnumber:	WAUZZZ4G5EN093887	Versionname:	A6 AVANT 136PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	104665	Power Kw:	100
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3515
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		


Degree of wear

	225/60/16/102 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm


Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	2483,25
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Roof, Chemical pollution, LI - Repair and paint (complete)	577,80
------------------------------------------------------------	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------




Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---------------------------------------------------------	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---------------------------------------------------------	--------



Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
-------------------------------------------------------------	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
---------------------------------------------------------	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
-------------------------------------------------------------	--------

