



BMW 3: 1EKN057

Vinnnumber:	WBA3K11080F818744	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	7/01/2013	Fiscalpower:	
Expertise Mileage:	110302	Power Kw:	100
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1106
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	934,96
-------------------	--------

Door panel F L, Scratch(es), Smart repair	110,64
---	--------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

<i>No pictures to display</i>	
Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door panel R R, Scratch(es), Smart repair 110,64



Bumper R, Damaged, LI - Repair and paint (complete) 211,80

