



VOLVO V90 CROSS COUNTRY: 1TBD430

Vinnnumber:	YV1PZA8B4J1021473	Versionname:	D4 4x4 Cross Country
First Registrationdate:	1/09/2017	Fiscalpower:	
Expertise Mileage:	10801	Power Kw:	140
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2227
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Sun Roof electric
Windows electric R	Panoramic roof
Cruise Control	Central consol F
Steering wheel multifunction	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	NOT OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/55/18/104 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1148,85
-------------------	---------


Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display

Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	--------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21

