



VOLVO V40: 1ENZ237			
Vinnnumber:	YV1MV8481D2035992	Versionname:	V40 D2 Base 115PK
First Registrationdate:	4/02/2013	Fiscalpower:	
Expertise Mileage:	161529	Power Kw:	84
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3214
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	205/55/16/91 MS LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1220,38
Seat cover F R, Stain, Forfeit			12,00



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	---------------



Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Door R L, Bump(s), PDR - Knock out without painting	63,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Seat cover F L, Stain, Forfeit	12,00
--------------------------------	-------



Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
--	--------

