



VOLKSWAGEN Passat: 1FXK497

Vinnnumber:	WVWZZZ3CZEE081365	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	27/11/2013	Fiscalpower:	
Expertise Mileage:	97688	Power Kw:	77
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2729
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2051,30
-------------------	---------

Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Rear window, Scratch(es), E - Replace

0,00



Interior, Dirty, Cleaning

50,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)

290,08



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

115,56



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

