



VOLKSWAGEN Passat: 1EOS635

Vinnnumber:	WVWZZZ3CZDE093340	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	8/02/2013	Fiscalpower:	
Expertise Mileage:	117002	Power Kw:	77
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1621
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	NOT OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2296,65
-------------------	----------------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------




Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper grille F R, Damaged, E - Replace 32,40



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Difference in color, Acceptable 0,00



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Roof pillar L, Bump(s), LI - Repair and paint (complete) 220,18



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Difference in color, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20

