



VOLKSWAGEN Touran: 1EMW232			
Vinnnumber:	WVGZZZ1TZDW070873	Versionname:	TOURAN Highline BMT St/St DSG 140PK Aut.
First Registrationdate:	25/01/2013	Fiscalpower:	
Expertise Mileage:	137810	Power Kw:	103
Bodytype:	MPV	Body color:	Red
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2724
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Total cost ex VAT	3294,79
Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Luggage space cover, Damaged, E - Replace 240,00



Bumper R, Damaged, Le - Replace and paint 651,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Door R L, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00

