



|                             |                         |              |                                |
|-----------------------------|-------------------------|--------------|--------------------------------|
| <b>HYUNDAI I40: 1TSZ726</b> |                         |              |                                |
| Vinnumber:                  | <b>KMHL81UADU045945</b> | Versionname: | <b>i40 BRE Style ISG 136PK</b> |
| First Registrationdate:     | <b>14/11/2012</b>       | Fiscalpower: |                                |
| Expertise Mileage:          | <b>125402</b>           | Power Kw:    | <b>100</b>                     |
| Bodytype:                   | <b>Break</b>            | Body color:  | <b>Black</b>                   |
| Gearbox:                    | <b>MAN 6 VIT</b>        | Paint type:  | <b>Metalic</b>                 |
| Transmission:               | <b>Front</b>            | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                   | <b>Diesel</b>           | Oil level:   | <b>OK</b>                      |
| Battery functioning:        | <b>Yes</b>              | Parking lot: | <b>1214</b>                    |
| Number of doors:            | <b>5</b>                |              |                                |
| Number of seats:            | <b>5</b>                |              |                                |
| Number head rests:          | <b>5</b>                |              |                                |
| Rims summer:                | <b>Aluminium</b>        |              |                                |
| Category:                   | <b>Passenger Car</b>    |              |                                |
| Oil level:                  | <b>OK</b>               |              |                                |

|                              |                              |                       |                          |
|------------------------------|------------------------------|-----------------------|--------------------------|
| <b>Options</b>               |                              |                       |                          |
| Radio CD                     |                              | Seats electric F L    |                          |
| Windows electric F           |                              | Central consol F      |                          |
| Windows electric R           |                              | Luggage cover         |                          |
| Cruise Control               |                              | Front parking sensors |                          |
| Steering wheel multifunction |                              | Rear parking sensors  |                          |
| Seats F heated               |                              | Type of Tow bar       | <b>Tow bar removable</b> |
| Radio multimedia             |                              |                       |                          |
| Type of headlighting         | <b>Headlighting Halogen</b>  |                       |                          |
| Type of GPS                  | <b>GPS big screen color</b>  |                       |                          |
| Type of Lining               | <b>Lining leather</b>        |                       |                          |
| Type of climate control      | <b>Autom climate control</b> |                       |                          |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position                       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission                        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake                           | <b>OK</b> |                     |            |

|                       |                                  |                    |       |                    |
|-----------------------|----------------------------------|--------------------|-------|--------------------|
| <b>Degree of wear</b> |                                  |                    |       |                    |
|                       | <b>205/60/16/92 V LightMetal</b> |                    |       |                    |
| Winter tyres:         | Fr.L.                            | <b>Other: 4 mm</b> | Fr.R. | <b>Other: 4 mm</b> |
|                       | Re.L.                            | <b>Other: 4 mm</b> | Re.R. | <b>Other: 4 mm</b> |

|                             |            |      |            |
|-----------------------------|------------|------|------------|
| <b>Assistance equipment</b> |            |      |            |
| Spare tyre compact          | <b>Yes</b> | Jack | <b>Yes</b> |

|                                      |               |
|--------------------------------------|---------------|
| Total cost ex VAT                    | <b>817,48</b> |
| Door panel R L, Damaged, E - Replace | <b>114,00</b> |




|  |             |
|--|-------------|
| Backrest cover F L, Deformed, Acceptable | <b>0,00</b> |
|--|-------------|



|  |              |
|--|--------------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

