



CITROEN JUMPER: 1TUR246

Vinnumber:	VF7YDUMGC12856542	Versionname:	
First Registrationdate:	5/08/2015	Fiscalpower:	
Expertise Mileage:	73522	Power Kw:	110
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV31
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/75/16/121 G Steel			
Winter tyres:	Fr.L.	Toyo: 4 mm	Fr.R.	Toyo: 4 mm
	Re.L.	Toyo: 4 mm	Re.R.	Toyo: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1476,17
Fuel cap cover, Missing, E - Replace	45,00



Bumper F R, Scratch(es), E - Replace	30,00
--------------------------------------	--------------




Glove box cover, Damaged, E - Replace	228,00
---------------------------------------	---------------



Certificate Of Conformity, Missing, E - Replace	0,00
---	------

No pictures to display

Roof, Bump(s), LI - Repair and paint (complete)	457,13
---	--------



Sidewalll RL (LCV), Damaged, Acceptable	0,00
---	------



Windscreen, Tear, E - Replace	395,40
-------------------------------	--------



Bumper F L, Scratch(es), E - Replace	30,00
--------------------------------------	-------



Door panel R L, Incomplete, E - Replace	34,00
---	-------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Interior, Damaged, E - Replace	35,00
--------------------------------	-------



Sidewalll RR (LCV), Damaged, Acceptable	0,00
---	------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), Smart repair	110,64
---	--------



Tailgate, Damaged, Acceptable	0,00
-------------------------------	------



Door panel R L, Incomplete, E - Replace 36,00



Interior, Dirty, Cleaning 75,00

