



CITROEN CACTUS: 1TUR376

Vinnumber:	VF70BBHY3GE502892	Versionname:	
First Registrationdate:	1/01/2028	Fiscalpower:	
Expertise Mileage:	55241	Power Kw:	
Bodytype:	Hatchback	Body color	Dark Red
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1117
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 1 mm	Fr.R.	Michelin: 1 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1019,90
-------------------	----------------

Air vent mid-dashboard, Incomplete, E - Replace	156,00
---	---------------



Rearview mirror glass L, Missing, E - Replace	18,00
---	--------------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), It - Spot repair 115,56



Bumper corner R L, Scratch(es), Smart repair 110,64



Interior, Dirty, Cleaning 96,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Smell, Ozone treatment 152,58

No pictures to display

Seat cover F R, Hole, Smart repair 64,32

