


BMW X1: 1TTR161

Vinnumber:	WBAVY11060VW86936	Versionname:	X1 sDrive16 116PK
First Registrationdate:	14/11/2012	Fiscalpower:	
Expertise Mileage:	119776	Power Kw:	85
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4215
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/94 V Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes
------------	------------

Total cost ex VAT	1549,89
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Wheel cover R R, Scratch(es), E - Replace 30,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Wing F L, Scratch(es), It - Spot repair 115,56



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Incomplete, E - Replace 32,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Bad repair, Acceptable 0,00





Wheel cover F R, Scratch(es), E - Replace 30,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display



Wheel cover R L, Scratch(es), E - Replace 30,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Wing F R, Bump(s), LI - Repair and paint (complete) 220,18



Seat cover F R, Dirty, Cleaning 12,00

