



OPEL Vivaro 2900: 1TTR145			
Vinnumber:	WOLF7B0A6CV631864	Versionname:	VIVARO 2900 B/F L1H1 DPF (EU5) 90PK
First Registrationdate:	6/07/2012	Fiscalpower:	
Expertise Mileage:	138246	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options	
Radio CD	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/65/16/106 T Steel			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment	
Spare wheel	Yes

Total cost ex VAT	899,04
Centre console, Hole, Smart repair	110,64



Front bumper, Damaged, E - Replace	398,40
------------------------------------	--------



Door moulding Lower F L, Missing, E - Replace	91,50
---	-------





Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Rearview mirror glass R, Broken, E - Replace	13,50
--	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Floor covering F L, Hole, E - Replace	237,00
---------------------------------------	--------



Interior, Dirty, Cleaning	48,00
---------------------------	-------

