



BMW X1: 1GGL480			
Vinnumber:	WBAVY11030VZ23642	Versionname:	X1 sDrive16 116PK
First Registrationdate:	3/02/2014	Fiscalpower:	
Expertise Mileage:	99534	Power Kw:	85
Bodytype:	SUV	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining artificial leather
Type of climate control:	Autom climate control


Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	225/50/17/94 H Steel			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm


Assistance equipment	
Runflat	Yes
Total cost ex VAT	638,91
Bonnet, Bad repair, Paint	0,00



Wheel cover R R, Scratch(es), E - Replace	30,00
-------------------------------------------	--------------



Wheel cover F L, Scratch(es), E - Replace 30,00



Wing F R, Bump(s) and scratch(es), It - Spot repair 115,56



Wheel cover F R, Scratch(es), E - Replace 30,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Sill outer R, Scratch(es), I - Repair 115,00

