



BMW X3: 1EDW977			
Vinnumber:	WBAWY310700A74230	Versionname:	X3 xDrive20 163PK Aut.
First Registrationdate:	2/11/2012	Fiscalpower:	
Expertise Mileage:	204918	Power Kw:	120
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	225/60/17/103 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			636,18
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16



Wheel arch cover R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display