



FORD S Max: 1EBH623			
Vinnumber:	WF0SXXGBWSCE48507	Versionname:	S-MAX Econetic Trend St&St DPF 115PK
First Registrationdate:	10/10/2012	Fiscalpower:	
Expertise Mileage:	89552	Power Kw:	85
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2501
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

























Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1967,96
Windscreen, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16



Bumper B. Scratch(es). Smart repair			110,64
--	--	--	---------------

Bumper R, Scratch(es), Smart repair			110,00
			
Door trim F R, Scratch(es), Smart repair			110,64
			
Bonnet, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Scratch(es), LI - Repair and paint (complete)			369,84
			
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Side window trim R R, Scratch(es), Smart repair			110,64
			
Wing R R, Bump(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R L, Scratch(es), LI - Repair and paint (complete)			382,02
			
Interior, Dirty, Cleaning			100,00
			
			
Door R R, Scratch(es), LI - Repair and paint (complete)			382,02
			
			
Rearview mirror basis L, Damaged, E - Replace			148,00

