



FORD Fiesta: 1GJM719			
Vinnnumber:	WF0DXXGAKDEY41566	Versionname:	FIESTA BER Trend ECONetic S/S 95PK
First Registrationdate:	25/02/2014	Fiscalpower:	
Expertise Mileage:	187718	Power Kw:	70
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1323
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	17565/65/14/88 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	1767,04
Luggage space cover, Damaged, E - Replace	192,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	---------------



Wheel cover F R, Scratch(es), E - Replace 24,00



Roof, Bump(s), LI - Repair and paint (complete) 529,20



Sill outer R, Scratch(es), LI - Repair and paint (complete) 248,40



Seat cover F R, Hole, Smart repair 64,32



Wing R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Rearview mirror housing R, Damaged, LI - Repair and paint (complete) 115,56

