



MERCEDES A: 1EOX130			
Vinnumber:	WDD1760121J061916	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	11/02/2013	Fiscalpower:	
Expertise Mileage:	73582	Power Kw:	80
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3820
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control


Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			60,00
Wheel cover F R, Scratch(es), E - Replace			30,00



Wheel cover F L, Scratch(es), E - Replace	30,00
---	--------------



Door R L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display