



**OPEL Astra: 1ABW253**

Vinnnumber:	<b>WOLPD8EG5B8025261</b>	Versionname:	<b>ASTRA BRE ECOTEC Enjoy FAP 110PK</b>
First Registrationdate:	<b>25/11/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>168718</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>161865 KM</b>	Parking lot:	<b>2822</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/50/17/94 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 4 mm</b>	Fr.R.	<b>Dunlop: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

Total cost ex VAT	<b>575,36</b>
-------------------	---------------

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>259,80</b>
---	---------------



Central pillar L, Scratch(es), Acceptable	<b>0,00</b>
---	-------------



Bodywork, Not original part, Remove lettering 75,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Interior, Stain, Cleaning 100,00



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Bonnet, Bump(s) and scratch(es), Acceptable 0,00



Door F R, Bump(s), Acceptable 0,00



Headlight L, Waterinfiltration, P - Check 0,00




Bumper R, Scratch(es), Acceptable 0,00



Luggage space cover, Incomplete, E - Replace 25,00



Door R R, Bump(s), Le - Replace and paint 0,00



Tailgate, Bump(s) and scratch(es), Acceptable 0,00



Door R L, Bump(s), Acceptable 0,00

