



AUDI A6: 1FME870			
Vinnumber:	WAUZZZ4G9EN029691	Versionname:	A6 AVANT 136PK
First Registrationdate:	14/08/2013	Fiscalpower:	
Expertise Mileage:	156967	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2104
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	225/60/16/98 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	2976,64
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Rear window, Scratch(es), E - Replace 0,00



Rocker panel inner R R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Damaged, Le - Replace and paint 766,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16

