



BMW 3: 1FCJ151

Vinnumber:	WBA3K11030F824046	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	23/05/2013	Fiscalpower:	
Expertise Mileage:	187495	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	652,80
-------------------	---------------

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------



Bumper grille F R, Damaged, E - Replace	32,40
---	--------------



Bumper moulding F M, Broken, E - Replace	14,40
--	--------------



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Engine, Tear, P - Check 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Damaged, LI - Repair and paint (complete) 211,80



Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper grille F L, Damaged, E - Replace 32,40



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display