



BMW 3: 1DTP677

Vinnumber:	WBA3D91040J218552	Versionname:	3 BER 316dA 116PK Aut.
First Registrationdate:	23/08/2012	Fiscalpower:	
Expertise Mileage:	82347	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3730
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	888,61
-------------------	--------

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,48
---	--------

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Roof, Bump(s), Acceptable 0,00

No pictures to display

Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover R R, Scratch(es), E - Replace 30,00

