



**LEXUS NX: 1LXG629**

Vinnnumber:	<b>JTJBJRBZ102033144</b>	Versionname:	<b>2.5 300H EXECUTIVE LINE</b>
First Registrationdate:	<b>23/12/2015</b>	Fiscalpower:	<b>4WD AUTO</b>
Expertise Mileage:	<b>92062</b>	Power Kw:	<b>145</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>7741 KM OVERSCHREDEN</b>	Parking lot:	<b>2725</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Seats electric F L	
Windows electric F	Seats electric F R	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

Winter tyres:	<b>225/60/18/100 H LightMetal</b>			
	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 312,96

Maintenance, Maintenance, Execute 0,00



Door F L, Damaged, Acceptable 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Scratch(es), Acceptable 0,00



Windscreen, Stone chip(s), Windscreen repair 58,80



Door F R, Bump(s), Acceptable 0,00

