



AUDI A5: 1EMR439

Vinnumber:	WAUZZ8T1DA044604	Versionname:	A5 SB TDie DPF 136PK
First Registrationdate:	24/01/2013	Fiscalpower:	
Expertise Mileage:	198872	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Body color:	met.
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	NOT OK	Oil level:	OK
Maintenance:	DEPUIS 1400 KM	Parking lot:	3233
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
Total cost ex VAT			1665,94
Seat cover F L, Stain, Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Repaired, P - Check			0,00
<i>No pictures to display</i>			
Seat cover F R, Stain, Acceptable			0,00
<i>No pictures to display</i>			
Spoiler R, Scratch(es), E - Replace			94,88



Door F L, Bump(s), LI - Repair and paint (complete) 478,02



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 88,20



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Trunk lid covering R, Incomplete, E - Replace 15,00



Centre console, Incomplete, E - Replace 15,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 350,16



Maintenance, Maintenance, Execute 0,00



Wing F R, Bump(s), Acceptable 0,00

No pictures to display

Boot cover, Missing, E - Replace 262,66



Door R R, Repaired, P - Check 0,00

No pictures to display