



| VOLKSWAGEN Golf: 1GJP288           |                          |              |                                |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber:                         | <b>WVWZZZAUZEP566729</b> | Versionname: | <b>GOLF VAR Highline 105PK</b> |
| First Registrationdate:            | <b>25/02/2014</b>        | Fiscalpower: |                                |
| Expertise Mileage:                 | <b>75767</b>             | Power Kw:    | <b>77</b>                      |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Blue</b>                    |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3330</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                                |
| Number of seats:                   | <b>5</b>                 |              |                                |
| Number head rests:                 | <b>5</b>                 |              |                                |
| Rims summer:                       | <b>Aluminium</b>         |              |                                |
| Category:                          | <b>Passenger Car</b>     |              |                                |
| Oil level:                         | <b>OK</b>                |              |                                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                |

| Options                        |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             |                              |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining semi-leather</b>   |
| Type of climate control        | <b>Autom climate control</b> |

| Limited Technical Inspection |            |                     |            |
|------------------------------|------------|---------------------|------------|
| Power steering               | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning            | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile           | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position                | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime          | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission                 | <b>OK</b>  |                     |            |
| Handbrake                    | <b>OK</b>  |                     |            |

| Degree of wear |                                  |                       |       |                       |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
|                | <b>205/55/16/91 T LightMetal</b> |                       |       |                       |
| Winter tyres:  | Fr.L.                            | <b>Michelin: 6 mm</b> | Fr.R. | <b>Michelin: 6 mm</b> |
|                | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

| Assistance equipment |            |
|----------------------|------------|
| Spare wheel          | <b>Yes</b> |

|  |        |
|--|--------|
| Total cost ex VAT  | 451,80 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00  |



|   |        |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover R L, Stain, Cleaning

50,00

