



**CITROEN C4: 1ENL613**

Vinnnumber:	<b>VF7NC9HP0DY504938</b>	Versionname:	<b>C4 BER Business GPS FAP</b>
First Registrationdate:	<b>30/01/2013</b>	Fiscalpower:	<b>92PK</b>
Expertise Mileage:	<b>108933</b>	Power Kw:	<b>68</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1629</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

























Total cost ex VAT 3169,84

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display		
Seat cover F L, Stain, Cleaning		25,00
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
		
Windscreen, Stone chip(s), E - Replace		487,20
		
Door F R, Scratch(es), LI - Repair and paint (complete)		318,35
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
		
Door panel F L, Dirty, Cleaning		25,00
		
Covering mid pillar L, Scratch(es), E - Replace		122,00
		
Rear spoiler, Chemical polution, LI - Repair and paint (complete)		115,56
		



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Bump(s), Acceptable 0,00

No pictures to display

Door panel F R, Dirty, Cleaning 25,00



Rear window, Scratch(es), E - Replace 370,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

