



VOLVO V60: 1EZH464

Vinnnumber:	YV1FW84A1D1138201	Versionname:	V60 D2 Kinetic St/St
First Registrationdate:	26/04/2013	Fiscalpower:	115PK
Expertise Mileage:	105720	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3125
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
	Tow bar removable

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	235/45/17/97 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1116,88
-------------------	----------------

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Protection plate M, Tear, E - Replace	74,00
---------------------------------------	--------------



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Rear window, Scratch(es), E - Replace 370,00

