



BMW 5 GT: 1EPW766

Vinnumber:	WBAXC01000DZ96622	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	114289	Power Kw:	135
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1223
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Front parking sensors	
Type of headlighting	Headlighting Xenon	Rear parking sensors	
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear








	275/40/19/101 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1828,97
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)		254,16



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21
	
Sill outer R, Scratch(es), LI - Repair and paint (complete)	372,60
	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Interior, Dirty, Cleaning	50,00
	
Alloy rim F L polished, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Protection plate M, Tear, E - Replace	74,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
