


MERCEDES C: 1GJN776

Vinnumber:	WDD2042021G297753	Versionname:	C BRE 220CDI BE Edition Avantgarde 163PK
First Registrationdate:	25/02/2014	Fiscalpower:	
Expertise Mileage:	121673	Power Kw:	120
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3622
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	333,18
-------------------	--------

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------


No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), PDR - Knock out without painting	63,00
	
Door F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	50,00

