



SKODA Octavia: 1AOC767			
Vinnumber:	TMBCT21Z4B2108934	Versionname:	OCTAVIA BER Ambiente DPF DSG 105PK Aut.
First Registrationdate:	18/02/2011	Fiscalpower:	
Expertise Mileage:	152812	Power Kw:	77
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2808
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm


Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1077,14
Bonnet, Bump(s), LI - Repair and paint (complete)			290,08



Wheel cover F R, Scratch(es), E - Replace	30,00
--	--------------



Roof, Bump(s), LI - Repair and paint (complete) 481,50



Interior, Dirty, Cleaning 100,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Wing R L, Bad repair, Acceptable 0,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Roof pillar R, Bad repair, Acceptable 0,00



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Tailgate, Bad repair, Acceptable 0,00

