



<b>BMW 5: 1HBV881</b>			
Vinnumber:	<b>WBA5C31050D949353</b>	Versionname:	<b>5 BER 520dA 163PK Aut.</b>
First Registrationdate:	<b>13/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>207479</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Dark Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2422</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 7 mm</b>	Fr.R.	<b>Michelin: 7 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>973,16</b>
<b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b>			<b>254,16</b>



<b>Wing R R, Scratch(es), LI - Repair and paint (complete)</b>			<b>369,84</b>
--	--	--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

