


PEUGEOT 308: 1HHG871

Vinnnumber:	VF3LC9HCGES141716	Versionname:	308 SW e-HDi Allure STT
First Registrationdate:	23/07/2014	Fiscalpower:	115PK
Expertise Mileage:	158699	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1526
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	1295,55
-------------------	---------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Damaged, LI - Repair and paint (complete)	462,35
---	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Covering mid pillar R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>		
Alloy rim R L polished, Damaged, LI - Repair and paint (complete)		143,00
Front bumper, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Door frame R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Steering wheel, Worn, P - Check		0,00
Seat F L compl, Worn, P - Check		0,00
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)		95,00
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L polished, Damaged, Acceptable		0,00
<i>No pictures to display</i>		
Rear bulkhead lining, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Damaged, LI - Repair and paint (complete)		452,20
Alloy rim R R polished, Damaged, LI - Repair and paint (complete)		143,00
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		