


BMW 116: 1ELJ970

Vinnnumber:	WBA1N310X0J710519	Versionname:	1 SPORTSHATCH 116d
First Registrationdate:	14/01/2013	Fiscalpower:	Eff.Dyn.Ed.116PK
Expertise Mileage:	167857	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	3715
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	157,79
-------------------	---------------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------



Wing F R, Scratch(es), 67 - Polish	55,19
------------------------------------	--------------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Front bumper, Repaired, P - Check

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Door F R, Bump(s), PDR - Knock out without painting

102,60



Door F L, Repaired, P - Check

0,00



Bumper R, Bump(s) and scratch(es), Acceptable

0,00



Wing F L, Repaired, P - Check

0,00



Bonnet, Bump(s), Acceptable

0,00



Wing R R, Bump(s), Acceptable

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

