



BMW 3 GRAN TURISMO: 1JPS728

Vinnumber:	WBA3Y11040GD87251	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	3/02/2015	Fiscalpower:	
Expertise Mileage:	99768	Power Kw:	100
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1528
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1209,47
Door R R, Scratch(es), LI - Repair and paint (complete)			318,35



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
--	---------------





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

211,80



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80

