


KIA Sportage: 1FXG434

Vinnumber:	USYPC815ADL413115	Versionname:	SPORTAGE 2WD Sense+
First Registrationdate:	26/11/2013	Fiscalpower:	115PK
Expertise Mileage:	102656	Power Kw:	85
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3613
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Firestone: 8 mm	Fr.R.	Firestone: 8 mm
	Re.L.	Firestone: 7,5 mm	Re.R.	Firestone: 7,5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	3815,50
-------------------	---------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Tailgate, Chemical polution, LI - Repair and paint (complete)	301,68
---	--------



Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing F R, Damaged, Le - Replace and paint 1082,52



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Damaged, Le - Replace and paint 1082,52



Sill outer R, Bump(s) and scratch(es), E - Replace 174,00



Windscreen, Stone chip(s), Windscreen repair 0,00




Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display